

Printing Tips on Brilliant+



Offering higher ink hold out, better dot definition, and a brighter, sharper result, the calandered surface of Brilliant is smoother, denser and less ink absorbent than traditional machine finished offsets, so reduced inking and fountain solution are recommended.

When using oxidative inks it is recommended that stacks be kept short and the use of spray powder where possible.

UCR (Under colour removal) or GCR (grey component replacement) is recommended in dense image areas to obtain the best results.

- We recommend “Speedy Dry” for use in combination with normal inks.
 - For further information contact your local specialist at CPI Inks
- Alternatively use fully oxidative inks without additives - (Speedy Dry is not compatible with oxidative inks)
- Minimal use of water will assist drying.
- Extended drying time may occur.
- Avoid the use of overnight inks.
- Low stack height recommended.
- Use of ink reducers slows drying.
- Use spray powder wherever possible.